

Work Order (Bid Form)

V	V	0	F	RK	0	RI	DE	R	IN	IF	O	RI	ΛA	TI	O	V

Work Order Name:

Work Order Type: Weatherization Audit Name: HAYWOOD

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0314

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE

Fax:

Henderson, TN

Email Address:

Agency Contact: Oliver, Jerry

Work Phone: Cell Phone:

Email Address:

Company Name & License Num	ber:
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-772-8957

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0314

Work Order Name:

Report Run On: 5/13/2010

Version 8.5.0 Page 1 of 6

Measures

	Measure 1 Infilt	ration Redctn			Component	ts		ı	nspected
C	omment								
					Estimated	ALCO CONTRACTOR OF THE PROPERTY OF THE PROPERT	# 3311 (-88-4027-7-77)	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal old flu and hole in kitchen. Seal exhaust vnet over cook stove.	Each	1		1771			
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal under kitchen sink and replace floor and repair leaks.Seal dryer vent repair wall behind dryer.	Each	1				The state of the s	
4	Labor	Labor	Each						
5	Construction Materials/Hardwar e	Laundry room seal wall to floor Repair wall behind washer and repair ceiling.	Hour	1			To any or a second		
6	Labor	Labor	Hour		Transport to				
7	Construction Materials/Hardwar e	Repair hall between bathroom and dinning room, Hall bath seal pipes under vanity	Each	1	1		TO THE PARTY OF TH		
8	Labor	Labor	Hour						
9	Construction Materials/Hardwar e	Repair ceiling in Ea bedroom 3x3 approx area and hole behind bed by bath.		1	1				
10	Labor	Labor	Hour						***************************************
11	Construction Materials/Hardwar e	NE bedroom repair hole in wall over heater. Hall bathroom repair spot	Each	1	The state of the s				
		approx 1x4 area above window			,				
12	Labor	Labor	Hour			A			
13	Construction Materials/Hardwar	Repair hole in floor in den.	Each	1		2			

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID: Alt. Client ID: 16016SW-0314

Work Order Name: Report Run On: 5/13/2010 Version 8.5.0 Page 2 of 6

14	Labor	Labor	Hour					at a same	
15	Construction Materials/Hardwar e	Caulk all widows inside and out	Each	1					
16	Labor	Labor	Hour			,			
2	Other Detail		443,74	[
					200 mm				
				Measur	e Sub Total:			Sub Total:	
Γ	Field Notes:								
									A BOARDS
7000	Measure 2 DWH	ł Pipe Insulation			Componen	ts			Inspected
	Measure 2 DWH omment	ł Pipe Insulation			Componen Estimated			Actual	Inspected
С		I Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspected
<i>C</i>	omment	•	<i>Units</i> Each		Estimated		Qty	Actual	
<i>C</i> # 1	omment Material / Labor	Description / Comment		Qty	Estimated		Qty	Actual	
C # 1	omment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated			Actual	
C # 1	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

	Measure 3 DWH	l Tank Insulation			Componen	ts			Inspected
C	comment								
					Estimated		04.	Actual	Total
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	ıotai
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	Labor	Each	1					
(Other Detail		[7		
L							<u> </u>		
-							<u> </u>		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
i	Measure 4 Attic	Ins. R-30			Componen	ts A1			Inspected
C	omment								
					Estimated			Actual	T-1-1
	Material / Labor	Description / Comment	Units	-	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - Add 10 inches	SqFt	1008					
2	Labor	Labor	Hour	1008					
2	Construction	Build attic access cover	Each	1		MANUAL MA			
3	Materials/Hardwar	Duild attic access cover	Edon	·			<u> </u>		
4	Labor	Labor	Hour						
C	Other Detail								
]		
									1
				Measur	e Sub Total:	F (A)] ,	Sub Total:	
	Field Notes:				1.0	A CONTRACTOR OF THE PROPERTY O			
									Exemples 5 (PO) VO
									e lambane i van
ļ									1

Client Name: Client ID: \ Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0314

Work Order Name: Report Run On: 5/13/2010 Version 8.5.0 Page 4 of 6

Measure 5 CO N	Monitor is Needed			Componen	ts		ſ	nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1				The state of the s	
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
	Any Other Heating Syste			Componen xygen deple Estimated	tion sens	sor.	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Counter Flow Direct vent 50-55 KBTU Natural gas heater	Each	1			Total according		
2 Labor	Labor	Hour	1					
Other Detail								
] [Canada planocard	
			Measur	e Sub Total:	ALL VICE		Sub Total:	
Field Notes:								

Report Run On: 5/13/2010

Page 5 of 6

Measure 7 Insta	all Kitchen Exhaust Fan			Componen	ts		/	nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Kitchen exhaust fan	Each	1				1 1 2	
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 8 Smo	ke Detector is Needed			Componen	ts			nspected
Comment				F** - 45 4 4			Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Smoke detector	Each	1	27777777				
2 Labor	Labor	Hour	1				The state of the s	
Other Detail			r	(—————————————————————————————————————		7 (
			L					
		200] []	Sub Tatal	
Field Notes:			Measur	e Sub Total:			Sub Total:	and the same of th
. , , , , , , , , , , , , , , , , , , ,								
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name:

Client ID: Alt. Client ID: 16016SW-0314 Work Order (Bid Form)

Work Order Name:

Report Run On: 5/13/2010

DOE Weatherization Assistant Version 8.5.0

Page 6 of 6